

# Instruction manual

## VWR® P6 Spectrophotometer

EU cat. no 634-1173



CE

UK  
CA



## Legal address of Manufacturer

### Europe

VWR International bv,  
Researchpark Haasrode 2020  
Geldenaaksebaan 464  
B-3001 Leuven  
+3216385011  
be.vwr.com

### UK Importer

VWR International Ltd  
Hunter Boulevard, Magna Park  
Lutterworth, Leicestershire, LE17 4XN  
uk.vwr.com

## Made in China

# Table of Contents

|                                                   |    |
|---------------------------------------------------|----|
| Safety Information .....                          | 1  |
| Package Contents .....                            | 1  |
| Unpacking .....                                   | 2  |
| Installation.....                                 | 2  |
| Intended use .....                                | 3  |
| Symbols and conventions .....                     | 3  |
| Product Specifications .....                      | 4  |
| Overview .....                                    | 5  |
| Getting Started .....                             | 5  |
| General Operating Instructions.....               | 6  |
| Basic Operation .....                             | 7  |
| Calibration and System Settings.....              | 1  |
| Measurement.....                                  | 5  |
| File management .....                             | 27 |
| User management and audit trail .....             | 28 |
| Formula editor.....                               | 33 |
| Performance verification.....                     | 34 |
| Troubleshooting .....                             | 40 |
| Repair and maintenance.....                       | 41 |
| User replaceable accessories and spare parts..... | 45 |
| Technical service.....                            | 46 |
| Warranty.....                                     | 47 |
| Compliance with local laws and regulations.....   | 47 |
| Equipment disposal .....                          | 48 |

# Safety Information

## Avoiding Electrical Shock

Please follow the guidelines below, and read this manual in its entirety to ensure safe operation of the unit.

VWR recommends against the use of P6 Spectrophotometer.



### To avoid electrical shock

- Do not open the device.
- Disconnect the device from the mains supply before carrying out maintenance work or changing the fuses.
- The inside of the device is a high-voltage area Danger!
- Do not use the device if it is damaged, especially if the main power cable way is in any damaged or defective.
- Repairs may only be carried out by the service technicians from your local VWR office and authorized contractual partners.
- The device must be connected to a power outlet that has a protective ground connection.
- If the equipment is used in a manner not specified by the manufacturer, the protection provided by the equipment may be impaired.



### Avoiding Damage to the Instrument

- Do not allow any liquid to enter into the device.
- Do not operate the device in a hazardous location or potentially explosive environment.

## Package Contents

| Description                               | Quantity |
|-------------------------------------------|----------|
| Spectrophotometer                         | 1PC      |
| Glass Cuvette                             | 4PCS     |
| Quartz Cuvette                            | 2PCS     |
| Power Cord ( Euro/UK/CH Plug )            | 3PCS     |
| Software USB Drive                        | 1PC      |
| USB Cable                                 | 1PC      |
| Quick Manual                              | 1PC      |
| Dust Cover                                | 1PC      |
| Fuse                                      | 1PC      |
| Tablet PC (With Power Adapter, Euro Plug) | 1PC      |

## Unpacking

Open the package, according to carefully check the packaging packing list items, if found inside the packaging are missing or damaged items please contact your local VWR/Avantor service provider or something similar.

## Installation

### Placement

Place the instrument on the stable table carefully.

### Connect the power cord


Check to confirm instrument power switch is turned off, the power cord plug into two separate power interface and power supply socket apparatus.

### Placement

Place the instrument on the stable table carefully.

### Connect the power cord

Check to confirm instrument power switch is turned off. Plug the female of the power cord into the power inlet of the instrument and plug the male into the power outlet.




|                  |                |
|------------------|----------------|
| 1 – Power inlet  | 2 – Power cord |
| 3 – Power outlet |                |

### Connect to Tablet with Bluetooth

Make sure that "Bluetooth" is turned on the tablet, and the user will need to start the spectrum analysis software to connect automatically.

### Connect to Tablet with USB Cable


Plug one end of the USB cable into the instrument's USB port (Type B, square) and the other end into the tablet PC's USB port (Type A, flat. If the tablet PC only has type C USB port, please use a type C to A adapter.).



|                                            |               |
|--------------------------------------------|---------------|
| 1 – USB port of tablet (Type A, flat)      | 2 – USB Cable |
| 3 –USB port of instrument (Type B, square) |               |

### Connect to computer with USB Cable

Plug one end of the USB cable into the instrument's USB port (Type B, square) and the other end into the computer's USB port (Type A, flat).



|                                            |               |
|--------------------------------------------|---------------|
| 1 – USB port of computer (Type A, flat)    | 2 – USB Cable |
| 3 –USB port of instrument (Type B, square) |               |

## Intended use

For research use only. Not intended for any animal or human therapeutic or diagnostic use.

## Symbols and conventions

The following chart is an illustrated glossary of the symbols that are used in this manual.

|  |                                                                                              |
|--|----------------------------------------------------------------------------------------------|
|  | <b>CAUTION</b> This symbol indicates a potential risk and alerts you to proceed with caution |
|--|----------------------------------------------------------------------------------------------|

|                                                                                   |                                                                                                              |
|-----------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------|
|   | <b>CAUTION</b> This symbol indicates the presence of high voltage and warns the user to proceed with caution |
|  | <b>CAUTION</b> This symbol indicates risks associated with hot surfaces                                      |

## Product Specifications

|                             |                                                                                                           |
|-----------------------------|-----------------------------------------------------------------------------------------------------------|
| <b>Optical System</b>       | Split Beam                                                                                                |
| <b>Wavelength Range</b>     | 190-1100nm                                                                                                |
| <b>Band Width</b>           | 1.5nm                                                                                                     |
| <b>Stray Light</b>          | ≤0.05%T @ 220nm & 360nm                                                                                   |
| <b>Photometric Range</b>    | 0 to 200%T, -0.3 to 3.0A, 0 to 9999C                                                                      |
| <b>Wavelength Accuracy</b>  | ±0.5nm                                                                                                    |
| <b>Photometric Accuracy</b> | ±0.3%T or ±0.004A @ 1A                                                                                    |
| <b>Stability</b>            | 0.0005A/h @ 500nm(After warming up for 1 hour)                                                            |
| <b>Baseline Flatness</b>    | ±0.001A                                                                                                   |
| <b>Language</b>             | English, French, German, Spanish, Portuguese, Chinese                                                     |
| <b>Display</b>              | TFT Color LCD (10.5", Touch Screen)                                                                       |
| <b>Storage</b>              | 64GB                                                                                                      |
| <b>Interface</b>            | USB-C, WIFI, Bluetooth, HDMI                                                                              |
| <b>Measuring Procedure</b>  | Photometry, Multi Wavelength, Kinetics, Time Scanning, Quantitation, Spectrum Scanning, Biological Method |
| <b>Power Supply</b>         | AC 100~240 V, 50~60 Hz, 120 W                                                                             |
| <b>Dimension</b>            | 456×360×185                                                                                               |
| <b>Weight</b>               | 11kg                                                                                                      |
| <b>Work Environment</b>     | 15 to 35°C, 15 to 70% relative humidity                                                                   |
| <b>Store Environment</b>    | -10 to 50°C, 15 to 70% relative humidity                                                                  |

This instrument is compliant to the European Directives on Low Voltage Directive 2014/35/EU, Electromagnetic compatibility 2014/30/EU.

Restriction on use of Hazardous Substances RoHS 2011/65/EU and their amendments.

## Overview

P6 Spectrophotometer used in Chemistry, Pharmaceuticals, Biochemical, Metallurgy, Light Industry, Textile, Material, Environments, Medical, Education and some other fields for Quality Control laboratories.

## Getting Started

The following chart describes the basic operation of the instrument.

### Turn the instrument power on/off

Press the blue button on the right of the instrument to start/shut down.

#### Note


*Do not turn the instrument on and off continuously and quickly. Wait at least 30 seconds before turning the instrument back on, otherwise the electrical and mechanical systems may be damaged.*

## Self-check and calibration

Check the instrument sample chamber and remove anything from the light path.



Launch the application UV Studio after double-clicking the icon on the windows desktop. The instrument starts self-test. Self-check includes the following steps: Turn on lamp and positioning light source switching mechanism → Positioning filter disc → Positioning slit switching mechanism (If Installed) → Positioning automatic sample holder (If Installed) → Get dark current → Positioning wavelength → Checking energy → Checking system baseline.



## User login

If the user has selected the “User Management and Audit Trail” module, after the self-test is completed, enter the “User Login” interface, select the user name and enter

the password and press “Login” to enter the system.



A login screen with a light blue background. At the top, the word "Login" is centered. Below it, there are two input fields. The first is labeled "User name" and contains the text "Admin" with a small person icon on the left and a right arrow on the right. The second is labeled "Password" and contains a small key icon on the left. At the bottom, there is a button with a blue square icon containing a white 't' and the text "Enter the system" below it.


## General Operating Instructions

### Touch screen using tips


The entire screen can be started with a touch. To make a choice, use your nails, fingertips, pencil, or stylus to press the screen. Don't press the screen with sharp objects (such as ball point).

### Using the keyboard

The instrument provides two kinds of keyboards for different situations. The numeric keypad is used to input parameters, and the full keyboard is used to input user information and file names.




A screen titled "Input Wavelength" with a teal header. Below the header, the text "500" is displayed in the center, with a small icon of a box with an 'X' on the right. Below this is a numeric keypad with a 4x3 grid of buttons. The buttons are labeled with numbers 1 through 9, 0, a hyphen/underscore, and a decimal point. At the bottom, there are two large buttons: a teal button with a white 'X' on the left and a teal button with a white checkmark on the right.



## Basic Operation

### Enter an application module

Main interface, press an application icon enter to measurement interface.



|                                                                                     |                                                                                                 |
|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------|
|  | <b>Photometry</b><br>Measuring the photometric value of a sample at a single wavelength.        |
|  | <b>Multi wavelength</b><br>Measuring the photometric value of a sample at multiple wavelengths. |

|                                                                                     |                                                                                                                                     |
|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------|
|     | <b>Kinetics</b><br>Measuring the change in absorbance or absorbance change rate over time at a specified wavelength.                |
|    | <b>Time scanning</b><br>Measuring the change of photometric value with time at a single wavelength.                                 |
|    | <b>Quantitation</b><br>Establish a standard curve and measure the concentration of the sample using a standard curve.               |
|    | <b>Biological method measurement</b><br>Measuring DNA, RNA and protein concentrations using built-in methods or new methods.        |
|    | <b>Spectrum scanning</b><br>Measuring the photometric curve of a sample over a range of spectra.                                    |
|    | <b>User management</b><br>Assign user rights, operate log management.                                                               |
|   | <b>Performance verification</b><br>Verify the technical performance of the instrument.                                              |
|  | <b>File management</b><br>Efficient management of user files, browsing, copying, renaming, and deleting operations.                 |
|  | <b>Custom method</b><br>Users can add calculation methods for special applications or exploratory studies according to their needs. |
|  | <b>System</b><br>Set system parameters and system calibration.                                                                      |

## Back to main interface

Measurement interface, press  back to main interface.

## Return to previous interface

Method/Settings/Data list/Curve list interface, press  back to previous interface.

## Do blank/Scan baseline

Measurement interface, put “Reference” in reference channel and measurement channel, press  to do blank/scan baseline.

## Measuring sample

Measurement interface, put “Reference” in reference channel and “Sample” in measurement channel, press  to do blank/scan baseline.

## Enter data /curve list

Measurement interface, press  to enter data/curve list.

## Measurement Results Operation

|                                                                                     |                                                                         |
|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------|
|    | <b>Open</b><br>Open a stored file, load data or parameters.             |
|    | <b>Save</b><br>Save data, parameters to storage.                        |
|    | <b>Print</b><br>Print test report.                                      |
|    | <b>Export to MS Word</b><br>Export file to MS Word format.              |
|  | <b>Export to MS Word file format</b><br>Export file to MS Excel format. |
|  | <b>Export to MS Word file format</b><br>Export file to PDF format.      |
|  | <b>Delete</b><br>Delete the selected results.                           |

# Calibration and System Settings



Select the icon in the main interface. Display options to calibrate the system and configure the basic instrument settings.

System tools

Calibration

>

Bandwidth

2.0(nm)

>

Light source

Tungsten lamp / deuterium lamp

2Hrs/2Hrs

>

Accuracy

Absorbance / transmittance / concentration

0.0000,0.00%,0.00

>

Language

English

>

Printer

>

General options

>

Type

P9

ID

U65T

Serial number

P

Hardware Version

1.0.0.1

Firmware Version

1.0.0.1

Software Version

1.0.0.1

Restore defaults

Engineer mode

## Calibration

Select the tab **Calibration** in the System interface. Remove something from the measurement channel, close the sample chamber cover, and select the item **Wavelength calibration**, **System baseline calibration** or **Dark current calibration** to do calibration.

**Important** Before performing the calibration, you must remove something from the measurement channel, close the sample chamber cover, and maintain this state throughout the calibration process.

Wavelength Correction

---

System baseline correction

---

Dark current correction

---

X

## Result resolution setting


Press the tab **Result resolution**. Select the resolution of the required display digits according to different measurement modes.

| Set accuracy |        |
|--------------|--------|
| Abs          | 0.0000 |
| %T           | 0.00   |
| Conce.       | 0.00   |

X ✓

## Light source management

Press the tab **Light source**, which displays the usage timing of the light source and the switching wavelength of the light source.



- Turn on/off lamp

Press the icon  to turn on/off Tungsten lamp/Deuterium lamp.

**Note**      *When using a single light source for a long time, you can turn off another unused light source to save light source life and energy.*

- Set the light source switching wavelength

Press the current switching wavelength, pop up the numeric keyboard, input the switching wavelength, and press the button  to complete the setting.


**Note**      *After modifying the light source switching wavelength, you need to calibrate system baseline.*

Press the icon  to reset the Tungsten lamp/Deuterium lamp timing.

**Note**      *To ensure the accuracy of the light source timing, perform the corresponding light source clear after replacing the light source. Do not operate at other times.*

## Language setting


Press the tab **Language** and select the desired language.



The screenshot shows a dialog box titled "Modify system language" with a teal header and footer. The header bar contains the text "Modify system language" in white. The main area is white and contains two selectable options: "English" and "简体中文" (Simplified Chinese), each followed by a horizontal line. The footer bar is teal and contains a white "X" icon in the center.

## Printer setting


Press the tab **Printer** and select the installed printer.



The screenshot shows a dialog box titled "set the printer" with a teal header and footer. The header bar contains the text "set the printer" in white. The main area is white and contains three selectable options: "Microsoft XPS Document Writer", "Microsoft Print to PDF", and "Fax", each followed by a horizontal line. The footer bar is teal and contains a white "X" icon in the center.

## General settings

Press the tab "General" to enter.



- **Warm up**

Press "Warm up", pop up numeric keyboard, input value 1~120 minutes, and press the button



to complete the setting.

- **Calibrate system baseline when boot**

Press the icon  to turn on/off the "Calibrate system baseline when boot" option.

## Measurement

### Important Guidelines

- Reagents and dilution buffers can cause cauterization and other damage to health.
- Samples (nucleic acids, proteins, bacteria cultures) can be infectious and cause serious damage to health.
- During sample preparation, measuring procedures and maintenance and cleaning work, observe all local laboratory safety precautions (e.g. wear protective clothing and gloves, use of disinfectant) regarding the handling of sample material.

- Dispose of measuring solutions and cleaning and disinfectant materials in accordance with the relevant local laboratory regulations.


## Check the cuvettes

The cuvettes must be clear and there's no remains of the samples on the surface of it. **Only Quartz cuvettes are permitted to be used in the range of UV area.**

## Photometry

**Photometry** mode is used to measure the absorbance or transmissivity of the sample at a single wavelength.

Main interface, press the icon  to start a **Photometry** application.



1. Press the icon  to switch to the measurement mode.

|            |                                               |
|------------|-----------------------------------------------|
| <b>Abs</b> | Measure absorbance value of the sample(s).    |
| <b>%T</b>  | Measure transmittance value of the sample(s). |

2. Press the button  to set wavelength, key in the measurement wavelength.
3. If the selection mode is Abs, you can calculate  $K \cdot A$  by pressing the button  to set the coefficient K.
4. Put the reference in the measurement channel and reference channel, press the button  to do blank.
5. Put the sample in the measurement channel, read the result.

## Multi-wavelength

**Multi-wavelength** mode is used to measure the absorbance or transmissivity of the sample at multiple wavelengths.

Main interface, press the icon  to start a **Multi-wavelength** application.

Mul WL 

| Number    | Mode            | Formula | WL(nm)   |
|-----------|-----------------|---------|----------|
| 0005/0005 | Absorbance(Abs) | A1-A2   | 810.0 nm |

Abs

# 0.0004

| A1     | A2     | A3     |  |  |  |  |  |  |  |
|--------|--------|--------|--|--|--|--|--|--|--|
| 500.0  | 575.0  | 810.0  |  |  |  |  |  |  |  |
| 0.0352 | 0.0348 | 0.0422 |  |  |  |  |  |  |  |
|        |        |        |  |  |  |  |  |  |  |
|        |        |        |  |  |  |  |  |  |  |

|      |                  |         |  |
|------|------------------|---------|--|
| Date | 2018/9/8 8:47:34 | Remarks |  |
|------|------------------|---------|--|

  
 Operation

  
 Method

  
 Blank

  
 Measure

1. **Multi-wavelength measurement** interface, press the button  to set the

measurement parameters. The method can be saved or directly called from the memory.

Press  to accept the new parameters and return to the measurement interface.

Multi WL Setting 

Photometric Mode Absorbance(Abs) >

---

WL. (nm) 3 >

|              |              |              |              |              |
|--------------|--------------|--------------|--------------|--------------|
| $\lambda 1$  | $\lambda 2$  | $\lambda 3$  | $\lambda 4$  | $\lambda 5$  |
| 500.0        | 575.0        | 810.0        | 365.0        | 398.0        |
| $\lambda 6$  | $\lambda 7$  | $\lambda 8$  | $\lambda 9$  | $\lambda 10$ |
| 420.0        | -----        | -----        | -----        | -----        |
| $\lambda 11$ | $\lambda 12$ | $\lambda 13$ | $\lambda 14$ | $\lambda 15$ |
| -----        | -----        | -----        | -----        | -----        |
| $\lambda 16$ | $\lambda 17$ | $\lambda 18$ | $\lambda 19$ | $\lambda 20$ |
| -----        | -----        | -----        | -----        | -----        |

Optical path(mm) 10 >

---

Equivalent Conversion 

Measure Count 3 >

Formula A1-A2 >

  
 Load Method

  
 Save Method

  
 Finish

|                       |                                                                                                                                                                        |
|-----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Photometric mode      | 2 photometric modes: absorbance, transmittance.                                                                                                                        |
| Wavelength            | 1~20 wavelengths are available, wavelength range: 190~1100nm.                                                                                                          |
| Cycles                | 1, 2, 3, 5, 10, 20, 30, 50 times can be selected, the instrument will calculate the average as the final output.                                                       |
| Calculation formula   | The instrument can choose to embed the calculation formula to directly calculate the result. The formula can support user customization (in the custom method module). |
| Optical path          | The width of the cuvette used for the measurement.                                                                                                                     |
| Equivalent conversion | Activation automatically converts measurements from different path cuvettes to values in the 10mm light path length.                                                   |

- Put the reference in the measurement channel and reference channel, close the sample chamber cover, and press the button  to do blank.

- ☐ \_\_\_\_\_
- ☐ \_\_\_\_\_
- ☐ \_\_\_\_\_




## Kinetics

**Kinetics** mode is used to measure the rate of change of the sample.



Main interface, press the icon  to start a **Kinetics** application.



1. **Kinetics measurement** interface, press the button  to set the measurement parameters. The method can be saved or directly called from the memory. Press the button  to accept the new parameters and return to the measurement interface.

**Kinetics Setting**
←

|                                 |                              |                       |                                        |
|---------------------------------|------------------------------|-----------------------|----------------------------------------|
| Kinetics Method                 | Kinetics >                   | Optical Path(mm)      | 10 >                                   |
| WL(nm)                          | 546.0 >                      | Equivalent Conversion | <input type="checkbox"/> OFF           |
| Background correction           | <input type="checkbox"/> OFF | Auto Adaption         | <input checked="" type="checkbox"/> ON |
| Correction WL(nm)               | >                            | YMax                  | >                                      |
| Total(S)                        | 120 >                        | YMin                  | >                                      |
| Interval(S)                     | 1 >                          | Auto Print            | <input type="checkbox"/> OFF           |
| Delay time/Differential time(S) | >                            | Auto Save             |                                        |
| Coefficient                     | >                            |                       |                                        |

New Method

Load Method

Save Method

Finish


|                       |                                                                                                                      |
|-----------------------|----------------------------------------------------------------------------------------------------------------------|
| Measurement mode      | 2 measurement modes: kinetics, kinetic rate.                                                                         |
| Wavelength            | Measured wavelength, range: 190~1100nm.                                                                              |
| Background correction | Background correction switch, can be set according to actual needs.                                                  |
| Corrected wavelength  | Background corrected wavelength, range: 190~1100nm.                                                                  |
| Total                 | Measure the total sampling time required.                                                                            |
| Interval              | Sampling interval.                                                                                                   |
| Delay/Derivative      | Waiting time before starting sampling/time of participating activity calculation.                                    |
| Coefficient           | Coefficient of activity calculation equation.                                                                        |
| Optical path          | The width of the cuvette used for the measurement.                                                                   |
| Equivalent conversion | Activation automatically converts measurements from different path cuvettes to values in the 10mm light path length. |
| Auto scale            | Whether to automatically adjust the coordinates based on the data.                                                   |
| Y max                 | The maximum value of the ordinate (valid only when the coordinates are fixed).                                       |
| Y min                 | Minimum value of the ordinate (valid only when the coordinates are fixed).                                           |
| Automatic printing    | Automatically print curves and results after measurement is complete.                                                |
| Automatic save        | Automatically save curves and results after measurement is complete.                                                 |

- Put the reference in the measurement channel and reference channel, close the sample chamber cover, and press the button  to do blank.
- Put the sample in the measurement channel, close the sample chamber cover, and press the button  to measure and get sampled data and draw the curve.
- Repeat step 3 to measure more samples.

# Time scanning

Time scanning mode is used to measure photometric value changes of the sample.

Main interface, press the icon  to start a Time scanning application.



1. Time scanning measurement interface, press the button  to set the measurement parameters. The method can be saved or directly called from the memory. Press  to accept the new parameters and return to the measurement interface.

Time Scan/Method Setting ⏮

|                       |                          |                    |                          |
|-----------------------|--------------------------|--------------------|--------------------------|
| Photometric Mode      | Absorbance(Abs) >        | Vertical Y Minimum | -0.0003 >                |
| WL. (nm)              | 500.0 >                  | Auto Print         | <input type="checkbox"/> |
| Scan Time(S)          | 1800 >                   | Auto Save          | <input type="checkbox"/> |
| Interval(S)           | 3 >                      |                    |                          |
| Optical path(mm)      | 10 >                     |                    |                          |
| Equivalent Conversion | <input type="checkbox"/> |                    |                          |
| Auto Adjust           | <input type="checkbox"/> |                    |                          |
| Vertical Y Maximum    | 0.0003 >                 |                    |                          |

New Method

Load Method

Save Method

Finish

|                       |                                                                                                                      |
|-----------------------|----------------------------------------------------------------------------------------------------------------------|
| Photometric mode      | 2 photometric modes: absorbance, transmittance.                                                                      |
| Wavelength            | Measurement wavelength, range: 190~1100nm.                                                                           |
| Total                 | Measure the total sampling time required.                                                                            |
| Interval              | Sampling interval.                                                                                                   |
| Optical path          | The width of the cuvette used for the measurement.                                                                   |
| Equivalent conversion | Activation automatically converts measurements from different path cuvettes to values in the 10mm light path length. |
| Auto scale            | Whether to automatically adjust the coordinates based on the data.                                                   |
| Y max                 | The maximum value of the ordinate (valid only when the coordinates are fixed).                                       |
| Y min                 | Minimum value of the ordinate (valid only when the coordinates are fixed).                                           |
| Automatic printing    | Automatically print curves and results after measurement is complete.                                                |
| Automatic save        | Automatically save curves and results after measurement is complete.                                                 |

- Put the reference in the measurement channel and reference channel, close the sample chamber cover, and press the button  to do blank.
- Put the sample in the measurement channel, close the sample chamber cover, and press the button  to measure and get sampled data and draw the curve.
- Repeat step 3 to measure more samples.

## Quantitation

**Quantitation** mode is used to measure sample concentration by establishing and using a standard curve.

**Main** interface, press the icon  to start a **Quantitation** application.

Quantitation


No.  
0013/0013
Formula  
Abs=0.1043°C-0.0025;A=A1
 

ppm

# 3.44

|    |        |  |  |  |  |  |  |  |  |
|----|--------|--|--|--|--|--|--|--|--|
| A1 | 485.0  |  |  |  |  |  |  |  |  |
|    | 0.3565 |  |  |  |  |  |  |  |  |
|    |        |  |  |  |  |  |  |  |  |
|    |        |  |  |  |  |  |  |  |  |

|   |        |      |                   |         |  |
|---|--------|------|-------------------|---------|--|
| A | 0.3565 | Date | 2018/9/8 13:47:27 | Remarks |  |
|---|--------|------|-------------------|---------|--|

  
 Operation


  
 Method

  
 Blank

  
 Measure

### Establish quantitative methods

- Quantitation measurement** interface, press the button  to enter into **Method** interface.



2. **Method** interface, press the button  to start a new measurement method and enter the parameter setting interface.

**Quantitation - New Method**

| Measurement           |              |              |              |              | Double WL Minus >         | Equation          | $C = f(Abs) >$            |
|-----------------------|--------------|--------------|--------------|--------------|---------------------------|-------------------|---------------------------|
| $\lambda 1$           | $\lambda 2$  | $\lambda 3$  | $\lambda 4$  | $\lambda 5$  |                           | Fitting           | Linear >                  |
| 546.0                 | 650.0        | ----         | ----         | ----         |                           | Zero Intercept    | <input type="radio"/> Off |
| $\lambda 6$           | $\lambda 7$  | $\lambda 8$  | $\lambda 9$  | $\lambda 10$ |                           | Calibration       | Measure standard sample > |
| ----                  | ----         | ----         | ----         | ----         |                           | Standard Quantity | 3 >                       |
| $\lambda 11$          | $\lambda 12$ | $\lambda 13$ | $\lambda 14$ | $\lambda 15$ |                           | Unit              | >                         |
| ----                  | ----         | ----         | ----         | ----         |                           | Threshold         | >                         |
| $\lambda 16$          | $\lambda 17$ | $\lambda 18$ | $\lambda 19$ | $\lambda 20$ |                           | Cuvette Matching  | <input type="radio"/> Off |
| ----                  | ----         | ----         | ----         | ----         |                           |                   |                           |
| Measure Count         |              |              |              |              | 1 >                       |                   |                           |
| Optical Path (mm)     |              |              |              |              | 10 >                      |                   |                           |
| Equivalent Conversion |              |              |              |              | <input type="radio"/> Off |                   |                           |


**Buttons:** Load Parameters, Save Parameters, From standard samples, Next

|                            |                                                                                                                                                                                                                                 |
|----------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Measurement                | Built-in single wavelength, dual wavelength difference, dual wavelength ratio, three wavelengths, area 5 ways, and support custom formula.                                                                                      |
| Wavelength                 | Measuring wavelength, range: 190~1100nm.                                                                                                                                                                                        |
| Circle                     | 1, 2, 3, 5, 10, 20, 30, 50 times can be selected, the instrument will calculate the average as the final output.                                                                                                                |
| Optical path               | The width of the cuvette used for the measurement.                                                                                                                                                                              |
| Equivalent conversion      | Activation automatically converts measurements from different path cuvettes to values in the 10mm light path length.                                                                                                            |
| Equation                   | Equation form: $C=F(Abs)$ and $Abs=F(C)$ .                                                                                                                                                                                      |
| Fitting                    | Three ways of fitting are provided: first order, second order, third order.                                                                                                                                                     |
| Zero intercept             | Turning on the representative fitting curve will directly cross the zero point, and closing will represent the fitting curve but the zero point.                                                                                |
| Calibration                | 3 ways to generate a standard curve: input equation coefficient method, standard sample method and input standard sample.                                                                                                       |
| Unit                       | Built-in 19 commonly used concentration units: -, %, ppm, ppb, g/l, mg/l, $\mu$ g/l, ng/l, g/dl, mg/dl, $\mu$ g/dl, mg/ml, $\mu$ g/ml, ng/ml, $\mu$ g/ $\mu$ l, ng/ $\mu$ l, mol/l, mmol/l, IU, and support input custom units. |
| Number of standard samples | The number of standard samples can be selected (only valid for standard sample calibration and standard sample input), quantity: 2~20.                                                                                          |
| Threshold                  | Upper and lower limits of measurement results.                                                                                                                                                                                  |

### 3. Establish standard curve

#### 3.1 Establish standard curve by inputting the equation coefficient


- 1) Set **Calibration** to **Input Equation Coefficient**, set other measurement parameters according to measurement requirements, and press the button  to start.
- 2) **Input Equation Coefficient** interface, press the coefficient  $K_0 \sim K_n$  to pop up the keyboard and enter the coefficient.




- 3) After the method is completed, the standard curve and related information are displayed. Press the button  to complete and return to **Method** interface.

### 3.2 Establish standard curve by measuring standard samples

- 1) Set **Calibration** to **Measure standard samples**, set other measurement parameters according to measurement requirements, and press the button  to start.




- 2) **Measure standard sample** interface, put the reference in the measurement channel and reference channel, close the sample chamber cover, and press the button  to do blank.
- 3) Put the standard sample in the measurement channel, close the sample chamber cover, and press the button  to measure.
- 4) Repeat step 3 to measure all standard samples.
- 5) Press the concentration cell to enter the corresponding concentration value.
- 6) After the method is completed, the standard curve and related information are displayed. Press the button  to complete and return to **Method** interface.




### 3.3 Establish standard curve by measuring standard samples

- 1) Set **Calibration** to **Input standard samples**, set other measurement parameters according to measurement requirements, and press the button → to start.



- 2) Press the **Abs** cell to input Abs value and press **Concentration** cell to input the corresponding concentration value.
- 3) After the method is completed, the standard curve and related information are displayed. Press the button  to complete and return to **Method** interface.



## Measure sample

1. **Quantitation measurement** interface, press the button  to enter into **Method** interface.
2. **Method** interface, load or new a method, press the button  to accept and return to measurement interface.
3. Put the reference in the measurement channel and reference channel, close the sample chamber cover, and press the button  to do blank.
4. Put the sample in the measurement channel, close the sample chamber cover, and press

the button  to measure and calculation results.

5. Repeat step 4 to measure more samples.

6. Press  to switch to list mode to browse the list of measurement results.

## Biological method

**Biological method measurement** mode is used to measure DNA, RNA and protein concentrations using built-in methods or new methods.

Main interface, press the icon  to start a **Biological method measurement** application.

DNA/Protein Analysis

No. 0006/0006 Formula  $C(\text{DNA})=62.9 \times (A1 - A_{\text{ref}}) - 36.0 \times (A2 - A_{\text{ref}})$ ;  $C(\text{Protein})=1552 \times (A2 - A_{\text{ref}}) - 757.3 \times (A2 - A_{\text{ref}})$

1.01<sup>mg/L</sup>

48.53<sup>mg/L</sup>

| A1     | A2     | Aref   | Ratio |  |  |  |  |  |  |
|--------|--------|--------|-------|--|--|--|--|--|--|
| 260.0  | 280.0  | 320.0  |       |  |  |  |  |  |  |
| 0.0940 | 0.1011 | 0.0000 | 0.87  |  |  |  |  |  |  |

| Date | 2018/9/8 10:56:27 | Remarks |  |
|------|-------------------|---------|--|
|      |                   |         |  |

Operation

Method Blank Measure

1 **Biological method measurement** interface, press the button  to enter into **Method** interface.

Protein Analysis - Measure

$$C(\text{DNA}) = (A1 - Aref) * 62.9 - (A2 - Aref) * 36.0$$

$$C(\text{protein}) = (A2 - Aref) * 1552.0 - (A1 - Aref) * 757.3$$

$$Ration = (A1 - Aref) / (A2 - Aref)$$

|                          |              |
|--------------------------|--------------|
| Biometric method         | DNA Method 1 |
| WL                       | 260.0, 280.0 |
| Measure count            | 1            |
| Equivalent Conversion    | Closed       |
| Light length(mm)         | 10           |
| Equation                 |              |
| Fitting                  |              |
| Zero Intercept           |              |
| Calibration              |              |
| Standard Sample Quantity |              |
| Unit                     | mg/L         |
| Threshold                |              |

New Method

Load Method

Save Method

OK

- 2 **Method** interface, press the button  to start a new measurement method and enter the parameter setting interface.

DNA/Protein Analysis/New Method

Method Name

DNA Method 1 >

|             |             |             |                   |                                     |
|-------------|-------------|-------------|-------------------|-------------------------------------|
| $\lambda 1$ | $\lambda 2$ | $\lambda 3$ | Background WL(nm) | <input checked="" type="checkbox"/> |
| 260.0       | 280.0       | 320.0       |                   |                                     |

Coefficient

62.9, 36.0, 1552.0, 757.3 >

Measure Count

1 >

Optical Path (mm)

10 >

Equivalent Conversion

☐

Unit

mg/L >

Threshold

>

Default

Load Parameters

Save Parameters

Finish


|                       |                                                                                                                                                                                                 |
|-----------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Measurement           | Built-in 7 methods: DNA-1(260/280), DNA-2(260/230), UV method, Lowry method, BCA method, CBB method, Biuret method.                                                                             |
| Wavelength            | Measure wavelength, range: 190~1100nm.                                                                                                                                                          |
| Coefficient           | Calculate the coefficient required for concentration (related to the specific measurement method)                                                                                               |
| Optical path          | The width of the cuvette used for the measurement.                                                                                                                                              |
| Equivalent conversion | Activation automatically converts measurements from different path cuvettes to values in the 10mm light path length.                                                                            |
| Unit                  | Built-in 19 commonly used concentration units: -, %, ppm, ppb, g/l, mg/l, µg/l, ng/l, g/dl, mg/dl, µg/dl, mg/ml, µg/ml, ng/ml, µg/µl, ng/µl, mol/l, mmol/l, IU, and support input custom units. |
| Threshold             | Upper and lower limits of measurement results.                                                                                                                                                  |

- 3 **Method** interface, load or new a method, press the button  to accept and return to measurement interface.
- 4 Put the reference in the measurement channel and reference channel, close the sample chamber cover, and press the button  to do blank.
- 5 Put the sample in the measurement channel, close the sample chamber cover, and press the button  to measure and calculation results.
- 6 Repeat step 5 to measure more samples.
- 7 Press  to switch to list mode to browse the list of measurement results.

## Spectrum scanning

**Spectrum scanning** mode is used to measure sample concentration by establishing and using a standard curve.

**Main** interface, press the icon  to start a **Spectrum scanning** application.



1. Spectrum scanning interface, press the button  to enter into **Method** interface.

**Spectrum Scan/Method**

|                                      |                    |                       |                              |
|--------------------------------------|--------------------|-----------------------|------------------------------|
| Photometry Mode                      | Transmittance(%) > | Equivalent Conversion | <input type="checkbox"/> OFF |
| Start WL. ( $\leq 1100.0\text{nm}$ ) | 1100.0 >           | Auto Adjust           | <input type="checkbox"/> OFF |
| End WL. ( $\geq 190.0\text{nm}$ )    | 190.0 >            | Y Maximum             | 0.03 >                       |
| Step(nm)                             | 1.0 >              | Y Minimum             | -0.03 >                      |
| Speed                                | Low(LS) >          | Auto Print            | <input type="checkbox"/> OFF |
| Loop (1 ~ 99)                        | 1 >                | Auto Save             | <input type="checkbox"/> OFF |
| Loop Interval                        | 10 >               |                       |                              |
| Optical Path (mm)                    | 10 >               |                       |                              |

Buttons: New Parameters, Load Parameters, Save Parameters, Finish


|                    |                                                                                |
|--------------------|--------------------------------------------------------------------------------|
| Measurement mode   | 2 measurement modes: kinetics, kinetic rate.                                   |
| Start wavelength   | Scan start wavelength, range: 190~1100nm.                                      |
| End wavelength     | Scan end wavelength, range: 190~1100nm.                                        |
| Interval           | 6 wavelength interval selectable 0.1, 0.2, 0.5, 1.0, 2.0, 5.0 nm               |
| Speed              | 3 scan speed selectable: Quick, Medium, Slow.                                  |
| Circle             | Scan times.                                                                    |
| Time interval      | Interval between 2 scans.                                                      |
| Optical path       | The width of the cuvette used for the measurement.                             |
| Auto scale         | Whether to automatically adjust the coordinates based on the data.             |
| Y max              | The maximum value of the ordinate (valid only when the coordinates are fixed). |
| Y min              | Minimum value of the ordinate (valid only when the coordinates are fixed).     |
| Automatic printing | Automatically print curves and results after measurement is complete.          |
| Automatic save     | Automatically save curves and results after measurement is complete.           |

- Put the reference in the measurement channel and reference channel, close the sample chamber cover, and press the button  to scan baseline.
- Put the sample in the measurement channel, close the sample chamber cover, and press the button  to scan sample and draw the curve.
- After the scan is complete, press the button  to zoom the graph as needed.
- Press the button  to retrieve the value of each point (peak) of the curve and mark it for a specific point.

# File management

**File management** is used to manage saved parameters, methods, and measurement files.

Main interface, press the icon  to start File management.



## Browse file list

**File management** interface displays the data files stored in the storage, including data, methods and parameters. Press **Measurement Mode** and **Type** to set the filter conditions and display the corresponding file types.

## Delete files

Select the file you want to delete to make it selected, then press the button  to delete it.

## Copy files

Select the files you want to copy to make it selected, then press the button  , pop up the **Path selection** form, select target path and press the button  .

**Rename file name**


Press the file name you want to rename, pop up the keyboard, enter a new file name, and press the  button to complete the modification.

**User management and audit trail**

**User management** is used to manage user permissions, operation logs, etc.

**Main interface**, press the icon  to start File management.

**Note**    *Only authorized users can enter the module to perform the corresponding operations. Usually an administrator or some advanced users.*




**GLP/GMP option**

**GLP/GMP option** contains four GLP/GMP options: "Automatic Data Saving", "Disable Overwriting

Data", "Allow Locking System" and "Password Replacement Period", which can be enabled/disabled by the administrator as needed.


Users and user groups

The module is divided into three layers of management structure. Each layer exists in the form of a group. All members belong to different groups. Group members in different levels can separately assign the permissions available for allocation within the level.




Operation of user groups

User management interface, press the tab **Group** to enter user group management.



- **Create a new user group**

Press the button  to create a new user group, assign the permissions that the group has, and press the button  when done.



- **Copy a user group**

Select the user group you want to copy, then press the button  to copy a user group with the same permissions, and press the button  to complete.

- **Edit a user group**

Select the user group you want to edit, then press the button  to edit a user group, and press the button  to complete.

## Operation of user


User management interface, press the tab **User** to enter user management.

- **Copy a user**

Select the user you want to copy, then press the button  to copy a user with the same permissions, and press the button  to complete.

- **Edit a user**

Select the user you want to edit, then press the button  to edit user name, description information, password, etc., and press the button  to complete.



| Edit user   |                                                                                           |
|-------------|-------------------------------------------------------------------------------------------|
| User name   | Admin >                                                                                   |
| Full name   | >                                                                                         |
| Password    | ***** >  |
| User group  | Administrator >                                                                           |
| Description | >                                                                                         |


- **Lock/unlock user**

Select the user who needs to lock/unlock, and then press the button  to lock the original active user.

It is temporarily unavailable. If you need to re-enable it, select the user to press the button  again.

## Audit trail

User management interface, press the tab Log to enter log management.



## Browse operation log

Press **User Name** to select the user who needs to browse the log. Press **Operation Time** to select the time range for viewing to view the operation log of one (or all) users.

## Print log

Select the log content you want to print and press the button  to print the log contents.

## Export log

Select the log content to be printed, press the button , and select the export path to export the log content.

## Database backup

Press the button  to back up the database to other storage after selecting the backup path.


## Database recovery

Press the button  to select the backed up database file to restore the database to the instrument default storage location.

# Formula editor


Method editor is used to write formulas for photometric calculations.

Main interface, press the icon  to start **Formula editor**.



## Add calculation formula

**Formula list** interface, press the button  to enter to **Formula editor** interface. Enter the formula name as required by pressing the label **Formula Name**, and select the applied module, and enter the calculation formula and press the button  to complete.




## Delete calculation formula

**Formula list** interface, select the method you want to delete and press the button  to delete the method.

## Performance verification

**Performance verification** is used to verify that the instrument's performance indicators are good.

**Main** interface, press the icon  to start **Performance verification**.



## Preparing

- The instrument must be warmed up for more than 30 minutes before performing performance verification.
- The instrument must first calibrate the dark current and the system baseline before verification.
- The reference material used for verification must be within the validity period of the test.

**Note** *Standard filters used to verify the performance of the instrument can be purchased separately from third parties or our company and are not configured with the instrument.*

## Wavelength accuracy and wavelength repeatability verification

### Standard material

Holmium oxide solution or equivalent filter

### Verification

- 1 **Performance Verification** interface, press the tab **Wavelength Accuracy**, press the button  to enter the **Setting** interface, set parameters, and press the button  to accept and back.

GMP/Wavelength accuracy setting ↶

Standard sample 1 

Holmium oxide

---

Measurement point and standard value 10 >

|       |       |       |       |       |
|-------|-------|-------|-------|-------|
| S1-1  | S1-2  | S1-3  | S1-4  | S1-5  |
| 640.9 | 536.9 | 485.3 | 451.3 | 416.7 |
| S1-6  | S1-7  | S1-8  | S1-9  | S1-10 |
| 361.1 | 333.6 | 287.7 | 278.2 | 241.3 |
| S1-11 | S1-12 | S1-13 | S1-14 | S1-15 |
| ----- | ----- | ----- | ----- | ----- |

Standard sample 2 

ND-5

---

Measurement point and standard value >

|       |       |       |       |       |
|-------|-------|-------|-------|-------|
| S2-1  | S2-2  | S2-3  | S2-4  | S2-5  |
| ----- | ----- | ----- | ----- | ----- |

Deviation(nm) ±0.3 >

---



- 2 Remove anything in the measurement channel, close the sample chamber cover, press the button  and select the tab **Wavelength Accuracy** to start the measurement.
- 3 According to the instructions of the instrument, put the reference into the measurement channel to do blank, then put the standard material into the measurement channel and display the test result after completion.

## Photometric accuracy and photometric repeatability verification

### Standard material

NIST 930D or equivalent filter

### Verification

- 1 **Performance Verification** interface, press the tab **Photometric Accuracy**, press the

button  to enter the **Setting** interface, set parameters, and press the button  to accept and back.

GMP/Photometric accuracy setting ⏮

|                                                                                                                                                 |       |                                                                                                                                                                     |       |                                                                                                                                                   |  |
|-------------------------------------------------------------------------------------------------------------------------------------------------|-------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------|---------------------------------------------------------------------------------------------------------------------------------------------------|--|
| Photometric mode                                                                                                                                |       | Transmittance(%T) >                                                                                                                                                 |       | Standard sample 3<br>T3 <span style="float: right;">ON </span> |  |
| Standard sample 1<br>T1 <span style="float: right;">ON </span> |       | Measurement point and standard value 3 >                                                                                                                            |       |                                                                                                                                                   |  |
| 440.0                                                                                                                                           | 546.0 | 635.0                                                                                                                                                               | ----- | -----                                                                                                                                             |  |
| 11.4                                                                                                                                            | 10.9  | 8.2                                                                                                                                                                 | ----- | -----                                                                                                                                             |  |
| Standard sample 2<br>T2 <span style="float: right;">ON </span> |       | Measurement point and standard value 4 >                                                                                                                            |       |                                                                                                                                                   |  |
| 440.0                                                                                                                                           | 546.0 | 635.0                                                                                                                                                               | ----- | 635.0                                                                                                                                             |  |
| 22.4                                                                                                                                            | 21.9  | 15.8                                                                                                                                                                | ----- | -----                                                                                                                                             |  |
|                                                                                                                                                 |       | Standard sample 4<br>Potassium Dichromate <span style="float: right;">ON </span> |       |                                                                                                                                                   |  |
|                                                                                                                                                 |       | Measurement point and standard value 4 >                                                                                                                            |       |                                                                                                                                                   |  |
| 235.0                                                                                                                                           | 257.0 | 313.0                                                                                                                                                               | 350.0 | -----                                                                                                                                             |  |
| 18.3                                                                                                                                            | 13.8  | 51.4                                                                                                                                                                | 23.1  | -----                                                                                                                                             |  |
|                                                                                                                                                 |       | Allowable deviation ±0.3 >                                                                                                                                          |       |                                                                                                                                                   |  |

   
Finish

- 2 Remove anything in the measurement channel, close the sample chamber cover, press the button  and select the tab **Photometric Accuracy** to start the measurement.
- 3 According to the instructions of the instrument, put the reference into the measurement channel to do blank, then put the standard material into the measurement channel and display the test result after completion.


## Stray light verification

### Standard material

10g/L NaI solution or equivalent filter (220nm), 50g/L NaNO<sub>2</sub> solution or equivalent filter (340 or 360nm).

### Verification

- 1 **Performance Verification** interface, press the tab **Stray Light**, press the button  to enter the **Setting** interface, set parameters, and press the button  to accept and back.



GMP/Stray light setting

| Photometric mode              | Transmittance(%T) > | Measurement WL >    |
|-------------------------------|---------------------|---------------------|
| Standard sample 1<br>Filter-1 | 220.0 >             | deviation ≤0.03%T > |
| Standard sample 2             | >                   |                     |
| Standard sample 3             | >                   |                     |
| Standard sample 4             | >                   |                     |

Finish

- 2 Remove anything in the measurement channel, close the sample chamber cover, press the button  and select the tab **Stray Light** to start the measurement.
- 3 According to the instructions of the instrument, put the reference into the measurement channel to do blank, then put the standard material into the measurement channel and display the test result after completion.


## Resolution verification

### Standard material

Toluene-hexane

### Verification

- 1 **Performance Verification** interface, press the tab **Resolution**, press the button  to enter the **Setting** interface, set parameters, and press the button  to accept and back.



| GMP/Resolution setting             |             |
|------------------------------------|-------------|
| Resolution calibration object name | Std-1 >     |
| Begin WL(nm)                       | 268.0 >     |
| End WL(nm)                         | 250.0 >     |
| Verification scope                 | 2.0nm, ≥2 > |

Finish

- 2 Remove anything in the measurement channel, close the sample chamber cover, press the button  and select the tab **Resolution** to start the measurement.
- 3 According to the instructions of the instrument, put the reference into the measurement channel to do blank, then put the standard material into the measurement channel and display the test result after completion.


## Spectral bandwidth verification

### Standard material

Air

### Verification

- 1 **Performance Verification** interface, press the tab **Spectral bandwidth**.



- 2 Remove anything in the measurement channel, close the sample chamber cover, press the button  and select the tab **Resolution** to start the measurement.

## Troubleshooting

Review the information in the table below to troubleshoot operating problems.

| Problem                 | Cause                                   | Solution                 |
|-------------------------|-----------------------------------------|--------------------------|
| Power on, no response   | Power cord connection is not reliable   | Improve connectivity     |
|                         | Fuse burning                            | Replace fuse             |
| Measurement uncertainty | Glass cuvettes used in UV Range         | Use quartz cuvettes      |
|                         | Sample is not Stable                    | Improve the sample       |
|                         | The concentration of sample is too high | Diluted sample           |
|                         | Power Supply Voltage Low or not Stable  | Improve the Power Supply |
|                         | Lamp damage or lamp life maturity       | Replace lamp             |

|                                    |                                                      |                                      |
|------------------------------------|------------------------------------------------------|--------------------------------------|
| Dark Current Error when self-check | The lid of the compartment is open during self-check | Close the lid, restart               |
| System Calibrate Failed            | Something block the Light path                       | Remove it, calibrate again           |
| Measurements inaccurate            | Cuvettes were contaminated                           | Clean cuvettes                       |
|                                    | Samples were contaminated                            | Improve samples                      |
|                                    | Worse matching of the cuvettes                       | Improve the matching of the cuvettes |
|                                    | Dark current error                                   | Resample dark current                |

## Repair and maintenance

### Daily Maintain

#### Check the compartment

After measurement, the cuvettes with sample solutions should be taken out of the compartment in time. Or the volatilization of the solution would make the mirror go moldy. Users must pay more attention to the corrosive sample and liquid easy to volatilize. Any solution remains in the compartment should be wipe off immediately.

#### Surface clean

The cover of the instrument is with paint. Please use wet towel to wipe off the drips on the surface immediately. Organic solution is forbidden to be used to clean the cover. Please wipe off the dirt on the cover timely.

#### Clean the cuvettes

After every test or after a solution change, the cuvettes should be cleaned carefully, or the remains on the surface would cause measuring error.

## Spare Parts Replacement

#### Replace the fuse



***Danger!*** Be sure to switch off the power and unplug the socket before replacement!

#### 1. Tools preparation

Prepare a 3×75 Flat Blade screwdriver.

**2. Switch Off the power supply**

Switch off the power supply, and unplug the socket.

**3. Take out the Fuse Seat**

Push the fuse case by using the screwdriver, and turn it counter clockwise, the fuse seat will pop out when released.



**4. Replace a new fuse**

Pick out the spare fuse (3.15A/250V) and replace it.



**5. Reset the fuse seat**

Replace the fuse seat in the power socket. Push the fuse case by using the screwdriver, and turn it clockwise, the fuse seat will be locked when released.



#### 6. Switch on the power

Plug the socket and switch on the power.

#### Replace lamps



**Hot!**

Wait 20 minutes before open the lamp chamber after power off to avoid scald!

#### 1. Tools preparation


Prepare a 6×150mm Flat Blade screwdriver and a pair of glove.

#### 2. Power Off

Switch off the power supply and unplug the socket.

#### 3. Open the cover

Loosen the indicated two screws and remove the lamp cover.



#### 4. Replace the D2 lamp


Unplug the connector(No. 1) .Unscrew the 2 screws on the D2 Flange (No.2) and remove the D2 lamp. Draw on the cotton glove and replace a new lamp. Fix the 2 screws and plug the connector again.



#### 5. Replace W lamp


*The Tungsten lamp is equipped with a blue-grey silicon coating by manufacturer. This coating is only a transport safety device. It can be removed with the first exchange of lamp.*

Pull out the defected W lamp and draw on the cotton glove. Insert the new W lamp as deep as possible on the lamp seat.



## 6. Adjust the position of the W lamp

Switch on the power(the Switch Mirror should be placed to the position as indicates). Observe the entrance facular, and it should in the center of the entrance hole. If the facular deviate to Left or Right, then loosen the two screws and move the lamp seat to Left or Right until it focus on the center of the slot. Then fix the screws.



## 7. Finish

Reset the cover of the light chamber and fix the screws. Reset the cover of the lamp room and fix the screws

## User replaceable accessories and spare parts

| Description                                     | Quantity | Cat. No. |
|-------------------------------------------------|----------|----------|
| CELL HOLDER, 4-CELL, 10MM                       | 1PC      | 634-6003 |
| CELL HOLDER, 4-CELL,10 TO 50MM                  | 1PC      | 634-6004 |
| CELL HOLDER, 4-CELL, 10 TO 100MM                | 1PC      | 634-6005 |
| CELL HOLDER, FOR CYLINDRICAL CELL               | 1PC      | 634-6006 |
| CELL HOLDER FOR TEST TUBES                      | 1PC      | 634-6009 |
| CELL HOLDER, WATER-JACKETED, 1 CELL, 10MM       | 1PC      | 634-1135 |
| CELL HOLDER FOR MICRO CELLS,BEAM HEIGHT:15MM    | 1PC      | 634-0687 |
| CELL HOLDER FOR TEST TUBES, D=16mm              | 1PC      | 634-1133 |
| CELL HOLDER,5-POSITION AUTO CELL CHANGER, 10 TO | 1PC      | 634-1136 |

|                                                |      |          |
|------------------------------------------------|------|----------|
| 100MM                                          |      |          |
| CELL HOLDER,8-POSITION AUTO CELL CHANGER, 10MM | 1PC  | 634-6010 |
| CELL HOLDER, SOLID SAMPLE                      | 1PC  | 634-6011 |
| CELL HOLDER, WATER-JACKED, 4 CELL, 10MM        | 1PC  | 634-1134 |
| CUVETTE, SQUARE.GLASS,10MM                     | 4PCS | 634-6013 |
| CUVETTE, SQUARE.GLASS,20MM                     | 2PCS | 634-6014 |
| CUVETTE, SQUARE.GLASS,30MM                     | 2PCS | 634-6015 |
| CUVETTE, SQUARE.GLASS,50MM                     | 2PCS | 634-6016 |
| CUVETTE, SQUARE.GLASS,100MM                    | 1PC  | 634-6017 |
| CUVETTE, SQUARE.QUARTZ,10MM                    | 2PCS | 634-6018 |
| CUVETTE, SQUARE.QUARTZ,20MM                    | 2PCS | 634-6019 |
| CUVETTE, SQUARE.QUARTZ,30MM                    | 2PCS | 634-6020 |
| CUVETTE, SQUARE.QUARTZ,50MM                    | 2PCS | 634-6021 |
| CUVETTE, SQUARE.QUARTZ,100MM                   | 1PC  | 634-6022 |
| CELL,QUARTZ, 100UL, 10MM, BEAM HEIGHT:15MM     | 1PC  | 634-0688 |
| CELL,QUARTZ, 200UL, 10MM, BEAM HEIGHT:15MM     | 1PC  | 634-0689 |
| CELL,QUARTZ, 500UL, 10MM                       | 1PC  | 634-6025 |
| FLOW CELL, 5 MM, GLASS, BEAM HEIGHT:15MM       | 1PC  | 634-0690 |
| FLOW CELL, 10 MM, GLASS, BEAM HEIGHT:15MM      | 1PC  | 634-0691 |
| FLOW CELL, 20 MM, GLASS, BEAM HEIGHT:15MM      | 1PC  | 634-0692 |
| FLOW CELL, 30 MM, GLASS, BEAM HEIGHT:15MM      | 1PC  | 634-0693 |
| FLOW CELL, 5 MM, QUARTZ, BEAM HEIGHT:15MM      | 1PC  | 634-0694 |
| FLOW CELL, 10 MM, QUARTZ, BEAM HEIGHT:15MM     | 1PC  | 634-0695 |
| FLOW CELL, 20 MM, QUARTZ, BEAM HEIGHT:15MM     | 1PC  | 634-0696 |
| FLOW CELL, 30 MM, QUARTZ, BEAM HEIGHT:15MM     | 1PC  | 634-0697 |
| PELTIER UNIT, A-1101                           | 1PC  | 634-1138 |
| SIPPER UNIT WITHOUT TEMP. CONTROL, A-1001      | 1PC  | 634-1139 |
| SIPPER UNIT WITH PELTIER TEMP. CONTROL, A-1201 | 1PC  | 634-1140 |
| SAMPLE ROOM PANEL WITH PORT                    | 1PC  | 634-1143 |
| FUSE, 3.15A/250V                               | 1PC  | 634-0651 |
| SOFTWARE STANDARD                              | 1PC  | 634-1182 |
| SOFTWARE AUDIT TRAIL                           | 1PC  | 634-1183 |

## Technical service

### Web Resources

Visit the VWR website at [www.vwr.com](http://www.vwr.com) for:

- Complete technical service contact information
- Access to the VWR Online Catalogue, and information about accessories and related products
- Additional product information and special offers

**Contact us** For information or technical assistance contact your local VWR representative or visit. [www.vwr.com](http://www.vwr.com).

### Warranty

**VWR** warrants that this product will be free from defects in material and workmanship for a period of two (2) years from date of delivery. If a defect is present, VWR will, at its option and cost, repair, replace, or refund the purchase price of this product to the customer, provided it is returned during the warranty period. This warranty does not apply if the product has been damaged by accident, abuse, misuse, or misapplication, or from ordinary wear and tear. If the required maintenance and inspection services are not performed according to the manuals and any local regulations, such warranty turns invalid, except to the extent, the defect of the product is not due to such non-performance.

Items being returned must be insured by the customer against possible damage or loss. This warranty shall be limited to the aforementioned remedies. IT IS EXPRESSLY AGREED THAT THIS WARRANTY WILL BE IN LIEU OF ALL WARRANTIES OF FITNESS AND IN LIEU OF THE WARRANTY OF MERCHANTABILITY.

### Compliance with local laws and regulations

The customer is responsible for applying for and obtaining the necessary regulatory approvals or other authorisations necessary to run or use the Product in its local environment. VWR will not be held liable for any related omission or for not obtaining the required approval or authorisation, unless any refusal is due to a defect of the product.

## Equipment disposal



This equipment is marked with the crossed out wheeled bin symbol to indicate that this equipment must not be disposed of with unsorted waste.

Instead it's your responsibility to correctly dispose of your equipment at lifecycle -end by handling it over to an authorized facility for separate collection and recycling. It's also your responsibility to decontaminate the equipment in case of biological, chemical and/or radiological contamination, so as to protect from health hazards the persons involved in the disposal and recycling of the equipment.

For more information about where you can drop off your waste of equipment, please contact your local dealer from whom you originally purchased this equipment.

By doing so, you will help to conserve natural and environmental resources and you will ensure that your equipment is recycled in a manner that protects human health.

Thank you





# Local VWR offices in Europe and Asia Pacific

## Austria

VWR International GmbH  
Graumannsgasse 7  
1150 Vienna  
Tel.: +43 1 97 002 0  
Email: info.at@vwr.com

## Belgium

VWR International BV  
Researchpark Haasrode 2020  
Geldenaaksebaan 464  
3001 Leuven  
Tel.: +32 016 385 011  
Email: vwr.be@vwr.com

## China

VWR (Shanghai) Co., Ltd  
Bld.No.1, No.3728 Jinke Rd,  
Pudong New District  
Shanghai, 201203- China  
Tel.: +400 821 8006  
Email: info\_china@vwr.com

## Czech Republic

VWR International s. r. o.  
Veetee Business Park  
Pražská 442  
CZ - 281 67 Strábrná Skalce  
Tel.: +420 321 570 321  
Email: info.cz@vwr.com

## Denmark

VWR International A/S  
Tobaksvejen 21  
2860 Søborg  
Tel.: +45 43 86 87 88  
Email: info.dk@vwr.com

## Finland

VWR International Oy  
Valimotie 17-19  
00380 Helsinki  
Tel.: +358 9 80 45 51  
Email: info.fi@vwr.com

## France

VWR International S.A.S.  
Immeuble Estréo  
1-3 rue d'Aurion  
93114 Rosny-sous-Bois cedex  
Tel.: 0 825 02 30 30\* (national)  
Tel.: +33 (0) 1 45 14 85 00  
(international)  
Email: info.fr@vwr.com  
\* 0,18 € TTC/ min + prix appel

## Germany

VWR International GmbH  
Hilpertstrasse 20a  
D - 64295 Darmstadt  
Freecall: 0800 702 00 07  
Tel.: +49 (0) 6151 3972 0 (international)  
Email: info.de@vwr.com

## Hungary

VWR International Kft.  
Simon László u. 4.  
4034 Debrecen  
Tel.: +36 (52) 521-130  
Email: info.hu@vwr.com

## India

VWR Lab Products Private Limited  
No.139. BDA Industrial Suburb,  
6th Main, Tumkur Road,  
Peenya Post,  
Bangalore, India – 560058  
Tel.: +91-80-28078400  
Email: vwr\_india@vwr.com

## Ireland / Northern Ireland

VWR International Ltd / VWR  
International (Northern Ireland) Ltd  
Orion Business Campus  
Northwest Business Park  
Ballycoolin  
Dublin 15  
Tel.: +353 01 88 22 222  
Email sales.ie@vwr.com

## Italy

VWR International S.r.l.  
Via San Giusto 85  
20153 Milano (MI)  
Tel.: +39 02-3320311/02-487791  
Email: info.it@vwr.com

## Korea

VWR International ~  
17, Daehak 4-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do  
Tel.: +82 31 645 7256  
saleskorea@avantorsciences.com

## Middle East & Africa

VWR International FZ-LLC  
DSP Laboratory Complex  
125, Floor 01  
Dubai, United Arab Emirates  
Tel.: +971 4 5573271  
info.mea@vwr.com

## The Netherlands

VWR International B.V.  
Postbus 8198  
1005 AD Amsterdam  
Tel.: +31 020 4808 400  
Email: info.nl@vwr.com

## Norway

VWR International AS  
Brynsalleen 4  
0667 Oslo  
Tel.: +47 22 90 00 00  
Email: info.no@vwr.com

## Poland

VWR International Sp. z o.o.  
Limbowa 5  
80-175 Gdansk  
Tel.: +48 058 32 38 210  
Email: info.pl@vwr.com

## Portugal

VWR International - Material de  
Laboratório, Lda  
Centro Empresarial de Alfragide  
Rua da Indústria, n° 6  
2610-088 Amadora  
Tel.: +351 21 3600 770  
Email: info.pt@vwr.com

## Singapore

VWR Singapore Pte Ltd  
18 Gul Drive  
Singapore 629468  
Tel: +65 6505 0760  
Email: sales.sg@vwr.com

## Spain

VWR International Eurolab S.L.  
C/ Tecnología 5-17  
A-7 Llinars Park  
08450 - Llinars del Vallès  
Barcelona  
Tel.: +34 902 222 897  
Email: info.es@vwr.com

## Sweden

VWR International AB  
Fagerstagatan 18a  
163 94 Stockholm  
Tel.: +46 08 621 34 00  
Email: info.se@vwr.com

## Switzerland

VWR International GmbH  
Lerzenstrasse 16/18  
8953 Dietikon  
Tel.: +41 044 745 13 13  
Email: info.ch@vwr.com

## UK

VWR International Ltd  
Customer Service Centre  
Hunter Boulevard  
Magna Park  
Lutterworth  
Leicestershire  
LE17 4XN  
Tel.: +44 (0) 800 22 33 44  
Email: uksales@vwr.com