


Physics

From classic and cutting-edge apparatus and demos, to time-saving activities, durable equipment, and essential supplies for your lab - we have what you need to turn physics lessons into physics connections.



Specifications:

Electrometer

- Electrometer gain factor: 1.00
- Input resistance: $>10^{12} \Omega$
- Output resistance: $<1 \text{ k}\Omega$
- Input current: $<10 \text{ pA}$
- Input capacitance: $<50 \text{ pF}$
- Max. output voltage: $\pm 8 \text{ V}$
- Resistance to excess voltage: 1 kV (from low-resistance sources), 10 kV (from high-resistance sources)
- Supply voltage: 12 V AC